

	Possible Solutions:		Remove & Replace Entire Ramp.	
	Surveyor Notes:		N/A	
	PROW/ADA:		Not Found, R304.2.2, R304.5.3	
	Total Cost:		\$ 1650.00	
Street 1 Name	ENTRANCE			
Stop Condition-Street 2	None			
Street 2 Name	N/A			
Stop Condition-Street 1	N/A			

