

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10090Main Street:ROSLYN_AVCross Street:S_TURNER_AVLocation:NADA ID: 904B9923C77BRamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	S TURNER AV	
Stop Condition-Street 2	StopSign	
Street 2 Name	N/A	
Stop Condition-Street 1	N/A	

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 1850.00

Comp	Field Measure Compliance Description		Compliance Description			Data
N/A	Ramp Length (in)	63.0	No	Ramp S	Slope (%)	13.6
No	Ramp Width (in)	47.5	No	Ramp >	2.2	
N/A	Flare Type LT	N/A	N/A	Flare T	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	lope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare T	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS P	rovided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS C	contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS L	ength (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS F	ull Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS C	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter	X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted	I X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk	2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk	2 Width (in)	N/A
	X Walk 1 Slope (%)	2.8		X Walk	2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.7		X Walk	2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp i	nside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear S	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear S	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm (Grate/Utility Hazard?	N/A
	Obstruction Type			Storm (Grate/Utility Type	
		N/A				N/A
			Yes	Surface	e Condition? (G/P)	Good





