## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51054 Main Street: MULBERRY_CHURCH_RD					Street:	N/A	Location:	SW		
ADA ID: 90FC51242E87	ID: 90FC51242E87 Ramp Type: BlendTrans1					nitial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	S L	Possible Solutions:			Compliance Description				liance Description	Data
		Remove & Replace Curb F Two New Directional Ram Equivalent.	Ram	o With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.2
			•		No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	2.6
Ann -			•	•	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CEEP AND	·				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A	The second	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
- A COL	The WAR A T				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second of the	The second of the				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
I want the total		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
The second se	A SAC				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		,		
	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second second	Not Found, R304.5.1, R304.5.3		2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
PROW/ADA: Not Found, R304.5.1, R304.5.3			04.3.	5	N/A	Painted X Walk1?	Yes		Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	116.0		X Walk 2 Width (in)	N/A	
Street 1 Name MULBERRY CHURCH RD						X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	YieldSign					X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A N/A
	N/A N/A				N/A		1.3		•	N/A N/A
Stop Condition-Street 2	N/A					Road Slope (%)			Clear Space?	
					<b>NI/A</b>	Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
		Tatal Orati	¢	2000.00	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

17.0