cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19935 Main Street: MORRISON_BV Cross Street: ADAIR_CT							1	014/	
Intersection ID: 19935	D: 19935 Main Street: MORRISON_BV		Cross	Street:		Location:	SW		
ADA ID: 92671688D7AA	1688D7AA Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
Total Contraction		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	10.6
and the second s		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Mor				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ARISO	AN A CALLER AND A			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	and the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
The second second		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
J. States		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
PROW/ADA:				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To SE
And the second of the second				N/A	X Walk 1 Width (in)	95.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ADAIR CT				X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	2.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	4.4
Street 2 Name	MORRISON BV			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

