

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44063 Main Street: SEDGEMOOR_LN Cross Street: GRAYWELL_LN Location: N

ADA ID: 93A8E6E9C2A2 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 42.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

GRAYWELL LN StopSign SEDGEMOOR LN None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	71.5	Yes	BlendTrans Slope (%)	3.0
	No	Ramp Width (in)	33.5	No	BlendTrans XSlope (%)	7.5
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	4.4
		X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	2.8
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	5.5		Clear Space?	N/A
		Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type		l	Storm Grate/Utility Type	
			N/A	l		N/A
				Yes	Surface Condition? (G/P)	Good
E	AL STATEMENT			N/A	Curb Slope (%)	2.7
	THE RESERVE THE PERSON NAMED IN					





