

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9085	Main Street: EASTWAY_DR			et: CURTISW	Location:	NW		
ADA ID: 94C091455C09	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance			nce: N	Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	8///	Possible Solutions:				Data Compliance Description		Data
		Remove & Replace Entire Ramp.	N/A	Ramp Leng	yth (in) 28.	) Yes	Ramp Slope (%)	6.9
	1 1 0.00		Yes	Ramp Widtl	h (in) 52.	No No	Ramp XSlope (%)	2.6
	2197		N/A	Flare Type	LT N/	N/A	Flare Type RT	N/A
	12 1		N/A	Flare Slope	e LT (%) N/	N/A	Flare Slope RT (%)	N/A
	1 1 M Barris		N/A	Flare Trave	rsable LT? N/	N/A	Flare Traversable RT?	N/A
07	3		N/A	Landing Lei	ngth (in) N/	N/A	DWS Provided?	N/A
CURTISWOOD_DR		Surveyor Notes:	N/A	Landing Wi	dth (in) N/	N/A	DWS Contrast?	N/A
	1 Age and	N/A	N/A	Landing Slo	ope (%) N/	N/A	DWS Length (in)	N/A
			N/A	Landing X S	Slope (%) N/	N/A	DWS Full Width?	N/A
Guistiens	A BELLA		N/A	Landing Cu	ırb? (Y/N) N/	N/A	DWS Offset (in)	N/A
	while the set		N/A	Shared Lan	nding? N/			
E A		PROW/ADA:	N/A	Gutter Pone	ding? N/	N/A	Gutter Slope (%)	N/A
# 68 C 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Not Found, R304.5.3	N/A			5 N/A	Gutter X Slope (%)	N/A
	Section Parties		N/A	Painted X V	Valk1? No	N/A	Painted X Walk2?	N/A
				X Walk 1 Di	irection To SV	,	X Walk 2 Direction	N/A
			N/A	X Walk 1 W	/idth (in) N//	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CU	RTISWOOD DR	_		X Walk 1 SI	lope (%) 2.3	;	X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 1 X	Slope (%) 1.3	2	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp insid	e XWalk1? N/	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope	e (%) N//	N/A	Clear Space?	N/A
				Road X Slo	pe (%) N//	N/A	Clear Space to XWalk (in)	N/A
			N/A			N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstruction	туре		Storm Grate/Utility Type	
					N//			N/A

**Yes** Surface Condition? (G/P)

Good

