## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 22519                   | Main Street: SHARON RD Cru |  |        |   | AYRSHIRE_PL             | Location:         | W     |                             |       |
|--|----------------------------|--|--------|---|-------------------------|-------------------|-------|-----------------------------|-------|
|  |                            |  |        |   |                         |                   |       |                             |       |
| ADA ID: 94FEF5439B7A Ramp Type: PerpDiag |                            | Initial Pass/Fail: Fail Overall Compliance: No |        |   |                         | o Severity Score: | 21.25 |                             |       |
| Codes/Mitigation Info/Possible Solution  |                            |  |        | Field Measurements/Component Compliance |                         |                   |       |                             |       |
|  | all i                      | Possible Solutions:                            |        | Comp                                    | ance Description Data C |                   | Comp  | Compliance Description      |       |
|  |                            | Remove & Replace Curb Ramp W                   | /ith   | N/A                                     | Ramp Length (in)        | 59.5              | No    | Ramp Slope (%)              | 10.4  |
|  |                            | Two New Directional Ramps or                   |        | No                                      | Ramp Width (in)         | 38.0              | Yes   | Ramp XSlope (%)             | 1.8   |
|  |                            | Equivalent.                                    |        | N/A                                     | Flare Type LT           | N/A               | N/A   | Flare Type RT               | N/A   |
|  |                            |  |        | N/A                                     | Flare Slope LT (%)      | N/A               | N/A   | Flare Slope RT (%)          | N/A   |
| A STATE OF                               |                            |  |        | N/A                                     | Flare Traversable LT?   | N/A               | N/A   | Flare Traversable RT?       | N/A   |
| Dime .                                   |                            |  |        | N/A                                     | Landing Length (in)     | N/A               | N/A   | DWS Provided?               | N/A   |
|  | 3 1                        | Surveyor Notes:                                |        | N/A                                     | Landing Width (in)      | N/A               | N/A   | DWS Contrast?               | N/A   |
| E B                                      | the second                 | N/A  |        | N/A                                     | Landing Slope (%)       | N/A               | N/A   | DWS Length (in)             | N/A   |
|  | 5 1 A                      |  |        | N/A                                     | Landing X Slope (%)     | N/A               | N/A   | DWS Full Width?             | N/A   |
|  |                            |  |        | N/A                                     | Landing Curb? (Y/N)     | N/A               | N/A   | DWS Offset (in)             | N/A   |
|  |                            |  | N/A    | Shared Landing?                         | N/A                     |                   |       |                             |       |
| 30 11 81 1                               |                            | PROW/ADA:                                      |        | N/A                                     | Gutter Ponding?         | N/A               | N/A   | Gutter Slope (%)            | N/A   |
| Second III                               | 1 P 21                     | Not Found, R304.5.1, R304.2.2                  |        | N/A                                     | Gutter Lip Ht (in)      | N/A               | N/A   | Gutter X Slope (%)          | N/A   |
|  |                            |  |        | N/A                                     | Painted X Walk1?        | No                | N/A   | Painted X Walk2?            | No    |
|  |                            |  |        |   | X Walk 1 Direction      | To SE             |       | X Walk 2 Direction          | To NE |
|  |                            |  |        | N/A                                     | X Walk 1 Width (in)     | N/A               | N/A   | X Walk 2 Width (in)         | N/A   |
| Street 1 Name                            | SHARON RD                  | -  |        |   | X Walk 1 Slope (%)      | 1.0               |       | X Walk 2 Slope (%)          | 0.2   |
| Stop Condition-Street 2                  | None                       |  |        |   | X Walk 1 X Slope (%)    | 0.2               |       | X Walk 2 X Slope (%)        | 1.9   |
| Street 2 Name                            | AYRSHIRE PL                |  |        | N/A                                     | Ramp inside XWalk1?     | N/A               | N/A   | Ramp inside XWalk2?         | N/A   |
| Stop Condition-Street 1                  | StopSign                   |  |        |   | Road Slope (%)          | 0.4               | N/A   | Clear Space?                | N/A   |
|  |                            |  |        |   | Road X Slope (%)        | 2.5               | N/A   | Clear Space to XWalk (in)   | N/A   |
|  |                            |  |        | N/A                                     | Any Obstructions?       | N/A               | N/A   | Storm Grate/Utility Hazard? | N/A   |
|  |                            | Total Cost: \$ 32                              | 200.00 |   | Obstruction Type        |                   |       | Storm Grate/Utility Type    |       |
|  |                            |  |        |   |                         | N/A               |       |                             | N/A   |

**Yes** Surface Condition? (G/P)

Good

