

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

3.6

0.7

N/A N/A N/A

N/A

N/A N/A N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

9.3

Good

Intersection ID: 7568 Main Street: LASSEN_BAY_PL Cross Street: TWEEDSMUIR_GLEN_LN Location: NW
ADA ID: 951CC17702C5 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
LASSEN BAY PL
Stop Condition-Street 1
None
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

PROW/ADA:
Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description		Data	Compl	iance	Description
N/A	Ramp Length (in)	44.5	Yes	Blend	dTrans Slope (%)
No	Ramp Width (in)	46.0	Yes	Blend	dTrans XSlope (%)
N/A	Flare Type LT	N/A	N/A	Flare	Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?
	X Walk 1 Direction	То Е		X Wa	lk 2 Direction
	X Walk 1 Width (in)	N/A		X Wa	ılk 2 Width (in)
	X Walk 1 Slope (%)	0.7		X Wa	ılk 2 Slope (%)
	X Walk 1 X Slope (%)	6.6		X Wa	ılk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?
	Road Slope (%)	6.6		Clear	Space?
	Road X Slope (%)	0.7	N/A	Clear	Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?
	Obstruction Type			Storn	n Grate/Utility Type
		N/A			

Yes

No

Surface Condition? (G/P)

Curb Slope (%)





