

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ARBOR VISTA DR Intersection ID: 46324 Cross Street: SENATOR ROYALL DR Location: SW **Overall Compliance: No** ADA ID: 957234257DE4 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

None

StopSign

Field Measurements/Component Compliance



ARBOR VISTA DR Street 1 Name Stop Condition-Street 2 Street 2 Name **SENATOR ROYALL DR** Stop Condition-Street 1

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Compliance Description N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) Landing Slope (%) N/A N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) N/A

X Walk 1 X Slope (%) 1.9 Ramp inside XWalk1? N/A Road Slope (%) 2.0 Road X Slope (%) 2.7 Any Obstructions? N/A N/A **Obstruction Type** N/A

Data	Com	pliance Description	Data
49.0	Yes	Ramp Slope (%)	5.7
43.5	Yes	Ramp XSlope (%)	0.6
N/A	N/A	Flare Type RT	N/A
N/A	N/A	Flare Slope RT (%)	N/A
N/A	N/A	Flare Traversable RT?	N/A
N/A	N/A	DWS Provided?	N/A
N/A	N/A	DWS Contrast?	N/A
N/A	N/A	DWS Length (in)	N/A
N/A	N/A	DWS Full Width?	N/A
N/A	N/A	DWS Offset (in)	N/A
N/A			
N/A	N/A	Gutter Slope (%)	N/A
N/A	N/A	Gutter X Slope (%)	N/A
No	N/A	Painted X Walk2?	No
To N		X Walk 2 Direction	To E
N/A	N/A	X Walk 2 Width (in)	N/A
2.6		X Walk 2 Slope (%)	3.1
1.9		X Walk 2 X Slope (%)	1.1
N/A	N/A	Ramp inside XWalk2?	N/A
2.0	N/A	Clear Space?	N/A
2.7	N/A	Clear Space to XWalk (in)	N/A
N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Storm Grate/Utility Type	
N/A			N/A
	Yes	Surface Condition? (G/P)	Good





Total Cost:



3200.00