

Access Compliance Report Public Rights-of-Way (Curb Ramps)



eet: CORSICA_FOREST_DR	t: CORSICA_FOREST_DR Cross Street: TOSCANA_WY						SE	
/pe: PerpDiag	Initial Pass	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
Possible Solutions:		Compliance Description			Data Compliance Description			
Remove & Replace Curb Ramp W	/ith N/A	Ram	np Length (in)	49.0	No	Ramp Slope (%)	8.8	
Two New Directional Ramps or		Ram	np Width (in)	48.0	No	Ramp XSlope (%)	2.2	
Equivalent.	N/A	Flar	e Type LT	N/A	N/A	Flare Type RT	N/A	
Surveyor Notes: N/A	N/A	Flar	e Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A			N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Land	ding Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A			N/A	N/A	DWS Contrast?	N/A	
	N/A	Land	ding Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A			N/A	N/A	DWS Full Width?	N/A	
A COLOR AND AND A COLOR			• • • • •	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shai	red Landing?	N/A		ζ, γ		
PROW/ADA: Not Found R304 2 2 R304 5 3	N/A	Gutt	ter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutt	ter Lip Ht (in)	N/A	N/A		N/A	
			,	No	N/A	Painted X Walk2?	No	
		XW	alk 1 Direction	To NW		X Walk 2 Direction	To SW	
	N/A	x w	alk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
-		XW	alk 1 Slope (%)	0.3		X Walk 2 Slope (%)	1.2	
			,	1.9		X Walk 2 X Slope (%)	1.0	
	N/A		,	N/A	N/A	Ramp inside XWalk2?	N/A	
		Roa	d Slope (%)	1.3	N/A	Clear Space?	N/A	
			,	1.9	N/A	•	N/A	
	N/A		• • • •	N/A	N/A		N/A	
Total Cost: \$ 32	200.00					Storm Grate/Utility Type		
				N/A			N/A	
	/pe: PerpDiag /Possible Solutions: Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3	Initial Pass Initial Pass Possible Solutions: Control Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Surveyor Notes: N/A N/A N/A PROW/ADA: N/A Not Found, R304.2.2, R304.5.3 N/A N/A N/A	Initial Pass/Fail: F /Possible Solutions: Compliance Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ram N/A Flar N/A Flar N/A Flar N/A Flar N/A Flar N/A Flar N/A Flar N/A Land Surveyor Notes: N/A Land N/A N/A N/A Land N/A Stand PROW/ADA: N/A M/A Gutt Not Found, R304.2.2, R304.5.3 N/A Gutt N/A XW XW N/A Rand Roa Roa Roa Roa N/A Rand Roa N/A Any XW N/A Rand Roa Roa Roa Roa N/A Any Roa N/A Any Roa Roa Roa Roa Roa Roa Roa N/A Any N/A Any<	Initial Pass/Fail: Fail Overall (Possible Solution Field Measure Possible Solutions: Compliance Description Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) N/A Ramp Length (in) Yes Ramp With (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) Surveyor Notes: N/A Landing Slope (%) N/A N/A Landing Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? PROW/ADA: N/A Gutter Lip Ht (in) N/A N/A Gutter Lip Ht (in) X Walk 1 Direction N/A X Walk 1 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) X Walk 1 X Slope (%)	Initial Pass/Fail: Fail Overall Complian Possible Solution Field Measurements/C Possible Solutions: Compliance Description Data Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 49.0 N/A Flare Type LT N/A Ramp Width (in) 48.0 N/A Flare Type LT N/A Flare Type LT N/A N/A Flare Taversable LT? N/A N/A Landing Width (in) N/A Surveyor Notes: N/A Landing Slope (%) N/A N/A Landing Slope (%) N/A N/A N/A Landing Slope (%) N/A N/A N/A Surveyor Notes: N/A Landing Slope (%) N/A N/A N/A N/A Landing Slope (%) N/A N/A N/A Gutter Ponding? N/A N/A N/A Gutter Ponding? N/A N/A N/A Gutter Lip Ht (in) N/A N/A Valk 1 Slope (%) 0.3 X Walk 1 Slope (%) 0.3 N/A Kamp	Pre: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Possible Solutions: Compliance Description Data Compliance Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 49.0 No N/A Ramp Udith (in) 48.0 No No N/A	Per PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: (Possible Solutions: Field Measurements/Component Compliance Description Data Compliance Description Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 49.0 No Ramp Slope (%) N/A Flare Type LT N/A N/A Flare Type RT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Flare Traversable RT? N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A DWS Contrast? N/A Landing Length (in) N/A N/A DWS Contrast? N/A N/A Landing Slope (%) N/A N/A DWS Contrast? N/A Landing Curb? (Y/N) N/A N/A DWS Contrast? N/A Landing Curb? (Y/N) N/A M/A DWS Foll With? N/A Gutter Ponding? N/A Gutter Slope (%) N/A PROW/ADA: N/A <t< td=""></t<>	

Yes Surface Condition? (G/P)

Good

