cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3506 Main St	Main Street: MT_HOLLY-HUNTERSVILLE_RIC ross Street: BEATTIES_FORD_RD							sw
				nil: Fail Overall (o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
Possible Solutions:		<u>c</u>					liance Description	Data
SPACE AND A LARCE	Remove & Replace Entire Ramp	. N	I/A	Ramp Length (in)	102.0	Yes	Ramp Slope (%)	5.5
SQ FOR			lo	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.3
		N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
NE RO	2 C	Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
THE STUD	4	N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
REALITION	1	N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TR. JOURS	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
1/1/1/2000		N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
2 - Frank Barris		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	I/A	Shared Landing?	N/A			
States	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Store States and State	Not Found, R304.5.1	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1	N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A A A A A A A A A A A A A A A A A A A	*C			X Walk 1 Direction	To N		X Walk 2 Direction	N/A
		N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name MT HOLLY-HUNTERSVILLE RD				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Signal				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A				Road Slope (%)	2.0	N/A	Clear Space?	N/A
				Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
		N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

