cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| · · · · · · · · · · · · · · · · · · · | | | | | | | | | |
|---|------------------------|---|---------|--|-----------------------|--------------|-----|-----------------------------|----------|
| Intersection ID: 32032 | Main Street: COLONY_RD | | Cross | Cross Street: WAKEHURST_RD | | | | Location: | NE |
| ADA ID: 986786651636 | Ramp Ty | Ramp Type: PerpDiag | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 33.75 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| Possible Solutions: | | | | Compliance Description Data Compliance | | | | | Data |
| | | | | N/A | | 48.0 | No | Ramp Slope (%) | <u> </u> |
| | | Remove & Replace Curb Ramp V Two New Directional Ramps or Equivalent. | • | N/A No | Ramp Length (in) | 46.0 45.0 | No | | 5.6 |
| | | | 01 | | Ramp Width (in) | | - | Ramp XSlope (%) | |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| WAKEHURST PD | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| 5 S | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, R304.5.1, R304.2 | 2.2, | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| L PROF | | R304.5.3 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SW |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | COLONY RD | | | | X Walk 1 Slope (%) | 7.1 | | X Walk 2 Slope (%) | 5.8 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 3.6 | | X Walk 2 X Slope (%) | 10.0 |
| Street 2 Name | ENTRANCE | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 3.9 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 7.5 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | ······ • | | | | N/A | | | N/A |
| | | | | | | 17/7 | Yes | Surface Condition? (G/P) | Good |
| | | | | | | | 162 | Surface Condition? (G/P) | Guu |

