cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · ·										
Intersection ID: 11521	Main Street: W_11TH_ST		Cros	Cross Street: N_CHURCH_ST				Location:	S	
ADA ID: 99C7E9E5E61C	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	27.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:					liance Description	Data		
		Remove & Replace Curb Ra	amn With	N/A	Ramp Length (in)	70.0	Yes	Ramp Slope (%)	5.3	
		Two New Directional Ramp	Ramps or	Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	2.4	
		Equivalent. Restripe Crosswalk(s To Provide Clear space. Remove Replace Gutter.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
			move &	N/A	Flare Slope LT (%)	9.9	No	Flare Slope RT (%)	10.4	
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
				No	Landing Length (in)	N/A	No	DWS Provided?	No	
		Surveyor Notes:		No	Landing Width (in)	N/A	N/A	DWS Contrast?	No	
		N/A		No	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				No	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No	
				N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A	
		4		N/A	Shared Landing?	No		()		
		PROW/ADA:		Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.4	
		Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.2.3, R305, R304.5.4	2 1	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.8	
			•	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
			,		X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
				N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	102.0	
Street 1 Name	W 11TH ST				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	3.7	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	2.0	
Street 2 Name	N CHURCH ST			Yes	Ramp inside XWalk1?	Yes	Yes	Ramp inside XWalk2?	Yes	
Stop Condition-Street 1	Signal			100	Road Slope (%)	0.1	N/A	Clear Space?	Yes	
	orginal				Road X Slope (%)	1.8	No	Clear Space to XWalk (in)	38.0	
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost:	\$ 4450.00	100	Obstruction Type	.10	100	Storm Grate/Utility Type	110	
			+ ++00.00			N/A		eterni orato, otinty Type	N/A	
						17/7	Yes	Surface Condition? (G/P)	Good	
							162		3000	

