## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

25.8

Intersection ID: 45682	Main Street: SOUTHPARK_LN		Cross	Street:	PARK_SOUTH_DR	Location:	SE		
ADA ID: 9A3003A2AB9F	Ramp Ty	Ramp Type: ParaDiag			ail: Fail Overall (	Severity Score:	26.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	40.0
		Two New Directional Ramps or		Yes	Ramp Width LT (in)	86.0	Yes	Ramp Width RT (in)	84.0
		Equivalent.		Yes	Ramp Slope LT (%)	0.9	No	Ramp Slope RT (%)	14.2
				Yes	Ramp XSlope LT (%)	0.6	No	Ramp XSlope RT (%)	2.5
A BAR STORE " A BAR	1 Santa			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Some Some	1 Sera			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E CHER	-	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	AN &	LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	PART AL			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	San Walter	R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
as 1 14 mo	AN AR	·····, ·····			X Walk 1 Direction	To W		X Walk 2 Direction	To NE
	the state of the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
A A A A A A A A A A A A A A A A A A A					X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	3.0
Street 1 Name	SOUTHPARK LN				X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	2.4
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	PARK SOUTH DR				Road Slope (%)	4.5	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

