

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.3

1.2

N/A

N/A

N/A

N/A

Intersection ID: 27747 Main Street: HANLIN\_CT Cross Street: LANSFORD\_RD Location: SW

ADA ID: 9B6FE368D124 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

Flare Traversable RT?

Data

61.0

40.0

N/A

N/A

N/A

N/A



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

HANLIN CT StopSign LANSFORD RD None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

PROW/ADA:
R304.5.1

Total Cost: \$ 3200.00

N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To E X Walk 2 Direction To N N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 4.1 X Walk 2 Slope (%) 1.3 X Walk 1 X Slope (%) 2.3 X Walk 2 X Slope (%) 1.7 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.8 N/A Clear Space? N/A N/A Road X Slope (%) Clear Space to XWalk (in) N/A 4.4 N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good



