## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4250	05 Main Str	eet: BULLOCK_GREENWAY_BV	Cross S	treet:	TOLLESON_AV			Location:	w
ADA ID: 9BA2948821				nitial Pass/Fail: Fail Overall Complian			ce. N		
									20.20
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
<u>а</u>		Possible Solutions:		Compliance Description		Data Compliance Description			Data
	1 1 1 1 1 1 1	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	64.0	No	Ramp Slope (%)	15.7
	BAS 10 TAN	Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
E Curse	A STATIST			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second secon	Se and			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and a last		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Sale at	C.C.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	ST.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
10 h - 6 + 1 9	A STREET			N/A	Shared Landing?	N/A			
	ALL ALL CARE	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
THE FREE AND	States of the second				X Walk 1 Direction	To SE		X Walk 2 Direction	To SW
Self-man and				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BULLOCK GREENWAY BV				X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	2.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	2.8
Street 2 Name	TOLLESON AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.4	N/A	Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

