cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12676 Main Street: HIGHLAND_AV Cross Street: HICKORY_GROVE_RD Location: NW ADA ID: 9C1A557B203C Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25 Codes/Mitigation Info/Possible Solution Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 35.0 No Ramp Slope (%) 9.0 N/A Flare Type LT N/A Ramp XSlope (%) 1.1 N/A Flare Slope LT (%) N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A N/A Provided? N/A
Field Measurements/Component Compliance Field Measurements/Component Compliance Possible Solutions: Compliance Description Data N/A Ramove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 35.0 No Ramp XSlope (%) 9.0 N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A
Possible Solutions: Compliance Description Data Compliance Description Data N/A Ramove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 35.0 No Ramp Slope (%) 9.0 N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A
N/ARamp Length (in)35.0NoRamp Slope (%)9.0N/AN/ARamp Directional Ramps or Equivalent.N/ARamp Width (in)43.5YesRamp XSlope (%)1.1N/AFlare Type LTN/AN/AFlare Type RTN/AN/AFlare Slope LT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/A
Image: Second
Two New Directional Ramps or Equivalent. No Ramp Width (in) 43.5 Yes Ramp XSlope (%) 1.1 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A
Equivalent. N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A Flare Traversable RT? N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A
N/A Landing Length (in) N/A DWS Provided? N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast? N/A
N/A N/A DWS Length (in) N/A
N/A Landing X Slope (%) N/A DWS Full Width? N/A
N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
N/A Shared Landing? N/A
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A
R304.5.1, R304.2.2 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A
N/A Painted X Walk1? No N/A Painted X Walk2? Yes
X Walk 1 Direction To S X Walk 2 Direction To E
N/A X Walk 1 Width (in) N/A N/A X Walk 2 Width (in) 117.0
Street 1 Name HICKORY GROVE RD X Walk 1 Slope (%) 4.5 X Walk 2 Slope (%) 1.0
Stop Condition-Street 2 None X Walk 1 X Slope (%) 0.7 X Walk 2 X Slope (%) 3.0
Street 2 Name HIGHLAND AV N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? Yes
Stop Condition-Street 1 StopSign Road Slope (%) 1.6 N/A Clear Space? N/A
Road X Slope (%) 2.3 N/A Clear Space to XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard? N/A
Total Cost: \$ 3200.00 Obstruction Type Storm Grate/Utility Type
N/A N/A

Yes Surface Condition? (G/P)

Good

