


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|----------------------|----------------------------|-------------------------------|------------------------|
| Intersection ID: N/A | Main Street: ALLEGIANCE DR | Cross Street: LADY LIBERTY LN | Location: NE |
| ADA ID: 9D111B141C00 | Ramp Type: BlendTrans1 | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 33.75 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
|--|---|-----|---|-----------------------|------|-----------------------------|-----------------------|------|
|  | Possible Solutions: | | Compliance | Description | Data | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | N/A | Ramp Length (in) | 49.0 | Yes | BlendTrans Slope (%) | 4.7 |
| | | | No | Ramp Width (in) | 43.0 | No | BlendTrans XSlope (%) | 8.4 |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| | Surveyor Notes: | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | | | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| PROW/ADA: | | N/A | Shared Landing? | N/A | | | | |
| R304.5.1, R304.5.3 | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | | | X Walk 1 Direction | To W | | X Walk 2 Direction | To S | |
| | | | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A | |
| | | | X Walk 1 Slope (%) | 2.7 | | X Walk 2 Slope (%) | 1.4 | |
| | | | X Walk 1 X Slope (%) | 2.7 | | X Walk 2 X Slope (%) | 4.1 | |
| | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | No | |
| | | | Road Slope (%) | 4.4 | | Clear Space? | N/A | |
| | | | Road X Slope (%) | 1.4 | N/A | Clear Space to XWalk (in) | N/A | |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | N/A | | N/A | |
| | | | | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | N/A | Curb Slope (%) | 0.4 | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Total Cost: \$ 3200.00

