

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: 4017	tersection ID: 4017 Main Street: GALLOWAY_RD			treet:	KENDAN_KNOLL_DR	Location:	SE		
ADA ID: 9D215CFCDA6	ID: 9D215CFCDA6B Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	S. Y. S. Landa	Possible Solutions:						Compliance Description Data	
	1 Post	Remove & Replace Curb Ramp Wir Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	9.7
ALC ALCONT				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.2
All and the second				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the state of the s				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ALLOW	IN RD			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Cha	300	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	THE THERE THE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6. B	and and a second			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	And			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	C C C C C C C C C C C C C C C C C C C			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A No
E C				IN/A	X Walk 1 Direction	To N	N/A	X Walk 2 Direction	To W
				N1/A		-	N/A		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GALLOWAY RD				X Walk 1 Slope (%)	7.8		X Walk 2 Slope (%)	2.8
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	1.9
Street 2 Name	KENDALL KNOLL DR			N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.6	N/A	Clear Space?	N/A
					Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

