

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14474Main Street:BROOKHILL_RDCross Street:S_TRYON_STLocation:NWADA ID: 9FB8BCAB7958Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	BROOKHILL RD
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	39.0	Yes	Ram	Slope (%)	5.2		
No	Ramp Width (in)	47.0	No	No Ramp XSlope (%)				
N/A	Flare Type LT	N/A	N/A Flare Type RT			N/A		
N/A	Flare Slope LT (%)	N/A	N/A	N/A Flare Slope RT (%)				
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)		N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)		N/A		
	X Walk 1 Slope (%)	6.4		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.3		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		
	The state of the s							





