
cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45985 Main S	Main Street: MASON_MILL_PL		Cross Street: WILLOW_VALLEY_CT				NW	
ADA ID: 9FDB6CF7DB03 Ramp	Ramp Type: BlendTrans1		Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:		Comp	Compliance Description Dat		a Compliance Description		Data	
LASON DALLAR 6 6	Remove & Replace Curb Ramp W	ith N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.2	
	Two New Directional Ramps or Equivalent.	No	Ramp Width (in)	46.0	No	BlendTrans XSlope (%)	6.0	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A		DWG Oliset (III)	N/A	
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			•			,		
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name MASON MILL PL			X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 None			X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 N/A			Road Slope (%)	4.0		Clear Space?	N/A	
			Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	



6.9





