

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16755	Main Str	eet: DICKINSON_PL	Cross Street: PRINCETON_AV				Location:	SE
ADA ID: A04E6F71ED09	Ramp Ty	Ramp Type: Directional1		Initial Pass/Fail: Fail Overall Compliance: I			o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description		Data	Data Compliance Description		Data
	A start	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	24.5	N/A	Grade Break?	N/A
	ANT AN		Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0
			No	Ramp Slope (%)	8.6	N/A	Grade Break XSlope (%)	0.0
			No	Ramp XSlope (%)	2.1			
A Designation of the second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	AN		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
C Plillo	- Report	Surveyor Notes:	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6	Com J	N/A	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
an analytic structure by	3 4		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	UP-CAL		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
A CARACTER AND A CARACTER ANTE ANO TER ANTE ANO TER ANTE ANO TER ANTE ANTE ANTE ANTE ANTE ANTE ANTE ANTE			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
and the second sec	B. C.	PROW/ADA:	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
THE LOLE BURN	Ky I I I	R304.2.2, R304.5.3	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	C C C C C	·····, ·····	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	Carl C		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N/A	Painted X Walk1?	No		Road Slope (%)	4.5
Street 1 Name	DICKINSON PL	-		X Walk 1 Direction	To SW		Road X Slope (%)	2.9
Stop Condition-Street 1	StopSign			X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A			X Walk 1 Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A			X Walk 1 X Slope (%)	2.9	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$ 1	600.00	Obstruction Type		Yes	Surface Condition? (G/P)	Good
					N/A	N/A	Curb Slope (%)	22.4

