

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.0

15.0

N/A

Good

Main Street: AVENTIDE LN Location: Intersection ID: 28730 **Cross Street: BANYAN CT** NE Initial Pass/Fail: Fail **Overall Compliance: No** 25 ADA ID: A22B4D42E7B0 Ramp Type: Perp **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

46.0

48.0

N/A

0.5

No

To S

N/A

5.1

10.5

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



	The second secon
Street 1 Name	BANYAN CT
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

POSSIDIE SOIULIOII			rieia ivie
Possible Solutions:	Compli	ance [Description
Remove & Replace Entire Ramp.	N/A	Ramp I	ength (in)
·	Yes	Ramp \	Width (in)
	N/A	Flare T	ype LT
	N/A	Flare S	lope LT (%)
	N/A	Flare T	raversable L1
	N/A	Landin	g Length (in)
Surveyor Notes:	N/A	Landin	g Width (in)
N/A	N/A	Landin	g Slope (%)
	N/A	Landin	g X Slope (%
	N/A	Landin	g Curb? (Y/N
	N/A	Shared	Landing?
PROW/ADA:	N/A	Gutter	Ponding?
Not Found, R304.5.3	N/A	Gutter	Lip Ht (in)
	N/A	Painted	I X Walk1?
		X Walk	1 Direction
	N/A	X Walk	1 Width (in)
		X Walk	1 Slope (%)
		X Walk	1 X Slope (%
	N/A	Ramp i	nside XWalk′

Table Training



Total Cost:



N/A

1850.00