

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



			•	<u> </u>	,					
Intersection ID: 10198	Main Street: FONTANA_AV				Cross Street: REMBERT_CT				Location:	NW
ADA ID: A3E4FC22963A	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 4		46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
A Company of the second	1 5	Remove & Replace	Entire Ramp.		N/A	Ramp Length LT (in)	32.0	N/A	Ramp Length RT (in)	26.5
	1				No	Ramp Width LT (in)	46.0	No	Ramp Width RT (in)	47.0
	B				Yes	Ramp Slope LT (%)	3.5	Yes	Ramp Slope RT (%)	7.8
et inter	SI I MA				No	Ramp XSlope LT (%)	7.9	No	Ramp XSlope RT (%)	5.7
	A II A				N/A	Ramp Length (in)	66.0	No	Ramp Slope (%)	8.4
	11th and the second sec				No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	4.3
Rom	ALL TO	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the second and the	L Contract	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	L.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second second	- AND				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the set is	a the second sec	1			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
and the second s	Mark The	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
All	-	Not Found, R304.5.	1, R304.5.1,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		R304.2.2, R304.5.3	, ,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A State way of	and the second				N/A	Shared Landing?	N/A			
The second se					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	FONTANA AV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	6.4		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 18	00.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
			•		2				Obstruction Type	
						and the second second				N/A
				the state of the s				N/A	Storm Grate/Utility Hazard?	N/A
				set from					Storm Grate/Utility Type	100
	A MARCE			the first	No. all	The second second				NI/A

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 36.1





