

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

11.8

		reet: COMMUNITY_HOUSE_RD							
Intersection ID: 28291	Main St	Cross Street: ARDREY_KELL_RD				Location:	SE		
ADA ID: A427FE08984B	B Ramp Type: Para			Fail: Fail	No Severity Score:	1.25			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Cor	Compliance Description Data			Compliance Description		
und The support of the		Remove & Replace Entire Ramp	N/A	Ramp Leng	th LT (in) 58	.0 N/A	A Ramp Length RT (in)	69.0	
The factor of the		· · ·	Yes	Ramp Width	n LT (in) 78	.0 Yes	s Ramp Width RT (in)	71.0	
	0		Yes	Ramp Slope	e LT (%) 3	.4 Yes	Ramp Slope RT (%)	8.1	
	RO		Yes	Ramp XSlo	pe LT (%) 1	.2 No	Ramp XSlope RT (%)	3.3	
5 6	And a minist		N/A	Landing Ler	ngth (in) N	A N/A	DWS Provided?	N/A	
AT EAR	9 - will the		N/A	Landing Wid	dth (in) N	A N/A	DWS Contrast?	N/A	
Y Xal		Surveyor Notes:	N/A	Landing Slo	pe (%) N/	A N/A	DWS Length (in)	N/A	
		LT RP < 5%	N/A	Landing X S	Slope (%) N	A N/A	DWS Full Width?	N/A	
	- 9 - 9 - 9 - 9 - 9 - 9 - 9 - 9 - 9 - 9		N/A	Landing Cu	rb? (Y/N) N/	A N/A	DWS Offset (in)	N/A	
E E			N/A	Shared Lan	ding? N	A			
			N/A	Gutter Pond	ding? N/	A N/A	Gutter Slope (%)	N/A	
		PROW/ADA:	N/A	Gutter Lip H	lt (in) N/	A N/A	Gutter X Slope (%)	N/A	
and a start of the	1 12	R304.5.3	N/A	Painted X W	Valk1? Ye	s N/A	A Painted X Walk2?	N/A	
and the second second		-		X Walk 1 Di	rection To	N	X Walk 2 Direction	N/A	
			N/A	X Walk 1 W	idth (in) 110	0 N/A	X Walk 2 Width (in)	N/A	
		2		X Walk 1 Slo	ope (%) 3	4	X Walk 2 Slope (%)	N/A	
Street 1 Name C	OMMUNITY HOUSE RD			X Walk 1 X	Slope (%) 1	3	X Walk 2 X Slope (%)	N/A	
Stop Condition-Street 1	YieldSign		N/A	Ramp inside	e XWalk1? Ye	s N/A	A Ramp inside XWalk2?	N/A	
Street 2 Name	N/A			Road Slope	(%) N/	A N/A	Clear Space?	N/A	
Stop Condition-Street 2	N/A			Road X Slop	pe(%) N/	A N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstrue	ctions? N/	A N/A	Storm Grate/Utility Hazard?	N/A	
				Obstruction	Туре		Storm Grate/Utility Type		
		Total Cost: \$ 10	600.00		N	A		N/A	
						Yes	Surface Condition? (G/P)	Good	

