

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Location: W ADA ID: A561109547C0 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Field Measurements/Component Compliance Possible Solution

	Codes/Mitigation Info/P
	A L. L.
L. L.	E. S.
E CHECO	E. E.

Surveyor Notes: N/A PROW/ADA:

**E MARTIN LUTHER KING JR BV** Street 1 Name Stop Condition-Street 1 Signal Street 2 Name N/A Stop Condition-Street 2

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Not Found, R304.5.3

N/A



Total Cost:



3200.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	72.0	Yes	BlendTrans Slope (%)	3.9	
Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	7.3	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
	X Walk 1 Width (in)	144.0		X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	3.3		Clear Space?	N/A	
	Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
			No	Curb Slope (%)	11.9	