

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15205	Main Street: CHEROKEE_RD			Cross	Street:	FENTON_PL	Location:	SW			
ADA ID: A5CB8B43ABD9	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description			
	Carlos Carlos	Remove & Replace Entir	e Ram	ıp.	N/A	Ramp Length (in)	96.0	N/A	Grade Break?	N/A	
	and the second			•	No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0	
Contraction of the second	and a 1	1			No	Ramp Slope (%)	9.4	N/A	Grade Break XSlope (%)	0.0	
	- 10				No	Ramp XSlope (%)	2.4				
		5			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A LA	10				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E & E		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
A A A A	199				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
A Y Sal					N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
A A A A A A A A A A A A A A A A A A A	1 24	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	9-1-6	R304.5.1, R304.2.2, R304	1.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
61. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		,,,,			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
PS PA	N V				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No		Road Slope (%)	0.5	
Street 1 Name	FENTON PL	_				X Walk 1 Direction	To SE		Road X Slope (%)	1.4	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.4	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	6.9	

