

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.6

3.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 16151 Main Street: FREELAND LN **Cross Street: S TRYON ST** Location: SW **Overall Compliance: No** ADA ID: A75E45223F75 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

No

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Data

66.0

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A



**S TRYON ST** Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solution	
Possible Solutions:	
Remove & Replace Entire Ramp.	
	,
	ı
Surveyor Notes:	
N/A	
PROW/ADA:	
Not Found, R304.2.2, R304.5.3	I

N/A Total Cost: 1850.00

N/A	Ramp Length (in)
Yes	Ramp Width (in)
N/A	Flare Type LT
N/A	Flare Slope LT (%)
N/A	Flare Traversable LT?
N/A	Landing Length (in)
N/A	Landing Width (in)
N/A	Landing Slope (%)
N/A	Landing X Slope (%)
N/A	Landing Curb? (Y/N)
N/A	Shared Landing?
N/A	Gutter Ponding?
N/A	Gutter Lip Ht (in)
N/A	Painted X Walk1?
	X Walk 1 Direction
N/A	X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%)
N/A	Ramp inside XWalk1?
	Road Slope (%)
	Road X Slope (%)
N/A	Any Obstructions?

Compliance Description







