

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.9

2.0

N/A

No

To SE

N/A

2.0

4.4

N/A

N/A

Intersection ID: 10024493 Main Street: CROWNPOINT_EXECUTIVE_DRCross Street: N/A Location: NE

ADA ID: A78286578831 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

82.0

43.0

N/A

No

N/A

4.9

3.9

N/A

4.9

To SW



Street 1 Name ENTRANCE
Stop Condition-Street 2 StopSign
Street 2 Name CROWNPOINT EXECUTIVE DR
Stop Condition-Street 1 None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:


N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00





Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Flare Traversable LT?

Flare Type LT

N/A

No

N/A



