

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48216 Main Street: BERRY_MILLER_CT Cross Street: ABERGLEN_DR Location: SW

ADA ID: A7AAE4D05533 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ABERGLEN DR None BERRY MILLER CT StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Compli	ance Description	Data	Compli	ance	Description	Data
	N/A	Ramp Length (in)	50.0	Yes	Ramp	Slope (%)	5.3
	No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	0.2
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Walk 1 Direction	To E		X Wal	k 2 Direction	To N
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.4		X Wal	k 2 Slope (%)	0.7
		X Walk 1 X Slope (%)	0.3		X Wal	k 2 X Slope (%)	3.6
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road Slope (%)	1.8	N/A	Clear	Space?	N/A
		Road X Slope (%)	1.1	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				Yes	Surfac	ce Condition? (G/P)	Good
gels.			,	•		` '	





