

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12473	Main Street: S_CLARKSON_ST			Cross Street: W_PALMER_ST				Location:	S	
ADA ID: A939EC6BD488	Ramp Type: Directional2			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)	53.0	N/A	Grade Break?	N/A	
				No	Ramp Width (in)	36.0	N/A	Grade Break Slope (%)	0.0	
	10 -			Yes	Ramp Slope (%)	5.1	N/A	Grade Break XSlope (%)	0.0	
	JA.			Yes	Ramp XSlope (%)	0.5				
	Y All			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Same.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
C C C	ANY VA	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
TSOM E	1997	NO CURB		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
Ausse	ALL.	1		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
34	The second			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	ALC: NO.			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	8 100	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
A A A A A A A A A A A A A A A A A A A		R304.5.1		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
Ser Vine	1 4 . 4			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
la tank in the second in the	and inter			N/A	Painted X Walk1?	No		Road Slope (%)	3.5	
Street 1 Name W	PALMER ST				X Walk 1 Direction	To NE		Road X Slope (%)	0.3	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.3	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1800.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	26.5	

