

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10844 Main Street: W_5TH_ST Cross Street: FRAZIER_AV Location: E

ADA ID: A93C094DA73D Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

FRAZIER AV StopSign W 5TH ST None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

r leid Measurements/Component Compnance						
Compliance Description		Data	Compliance Description		Data	
N/A	Ramp Length (in)	57.0	No	Ramp Slope (%)	8.4	
No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	10.5	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	8.7		X Walk 2 Slope (%)	0.6	
	X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	10.0	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	9.6	N/A	Clear Space?	N/A	
	Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A	

N/A N/A

N/A

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

Obstruction Type