

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	<u> </u>	<u> </u>						
Intersection ID: 15005	Main Str	Cross Street: TELEVISION_PL					Location:				
ADA ID: A9444950C51D	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 22		22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			Data	
ATTA . M	0// 34	Remove & Repla	ace Entire Ramp.		I/A	Ramp Length LT (in)	58.0	N/A	Ramp Length RT (in)	62.0	
	11 120		P-		/es	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0	
	1 3			١	/es	Ramp Slope LT (%)	0.7	No	Ramp Slope RT (%)	9.1	
A A A A A A A A A A A A A A A A A A A	1.42			1	lo	Ramp XSlope LT (%)	4.2	No	Ramp XSlope RT (%)	2.8	
	11 Alexandre			I	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	3.6	
	<u>e</u>			I	No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.5	
55	1 1 .	Surveyor Notes:		I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
<u>していていていていていていていていていていていていていていていていていていてい</u>	1222	LT RP < 5%		I	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Sector Marine Level				I	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
and the second	60			I	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	all main and a			I	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A start to a	And I	PROW/ADA:		I	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
- Harden Carton	1400 S St.	Not Found, R30	4.5.1, R304.5.3,	I	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6.		R304.3.2	, ,	I	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	ALL STORE AND			I	N/A	Shared Landing?	N/A				
A de la contra de				I	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign			1	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	PAUL BUCK BV			I	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 18	300.00 I	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
								N/A	Any Obstruction?	N/A	
									Obstruction Type		
		and the second second		and freedow						N/A	
				11	-	and the second		N/A	Storm Grate/Utility Hazard?	N/A	
				11					Storm Grate/Utility Type	IN/A	
					1					N/A	

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 20.5





