

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

24.0

72.0

5.5

3.4

8.5

7.3

N/A

No

N/A

1.1

2.8

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 5.9

To NW

Intersection ID: 50240 Main Street: LONGSTONE_LN Cross Street: CEDAR_WALK_LN Location: SW

ADA ID: A9EF3FE8F34C Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None LONGSTONE LN StopSign CEDAR WALK LN Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.


Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost:



3.7

0.9

N/A

N/A

N/A

Yes

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







Road Slope (%)

Road X Slope (%)

3200.00