

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 3373 M	Main Street: KATELYN DR		: PROSPERITY_CHUR	Location:	S	
	Ramp Type: Perp					10
· · · ·		Initial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance				
	Possible Solutions:	Com	pliance Description	Data	Compliance Description	Data
6 7 5	Remove & Replace Entire Ramp	. N/A	Ramp Length (in)	71.5	Yes Ramp Slope (%)	7.9
		No	Ramp Width (in)	36.5	No Ramp XSlope (%)	3.0
Ange &		N/A	Flare Type LT	N/A	N/A Flare Type RT	N/A
A CONTRACTOR OF A CONTRACTOR O		N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)	N/A
E. S. L.		N/A	Flare Traversable LT?	N/A	N/A Flare Traversable RT?	N/A
	and the second se	N/A	Landing Length (in)	N/A	N/A DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A DWS Length (in)	N/A
8		N/A	Landing X Slope (%)	N/A	N/A DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A DWS Offset (in)	N/A
a 1 1/ Destar and		N/A	Shared Landing?	N/A		
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A Gutter Slope (%)	N/A
The second second	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A Gutter X Slope (%)	N/A
A DATE A		N/A	Painted X Walk1?	Yes	N/A Painted X Walk2?	N/A
1 Com Contraction of the second			X Walk 1 Direction	To NE	X Walk 2 Direction	N/A
L CONTRACTOR		N/A	X Walk 1 Width (in)	107.0	N/A X Walk 2 Width (in)	N/A
Street 1 Name PROSPERITY CHUR	CH RD		X Walk 1 Slope (%)	4.9	X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	1.9	X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	Yes	N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A		Road Slope (%)	N/A	N/A Clear Space?	N/A
			Road X Slope (%)	N/A	N/A Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00	Obstruction Type		Storm Grate/Utility Type	
				N/A		N/A

