

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.0

9.9

N/A

No

N/A

2.2

6.3

N/A

N/A

N/A

N/A

N/A

Good

Surface Condition? (G/P)

To NE

Main Street: OAKTON HUNT DR **Cross Street: WRAYHILL DR** Location: Intersection ID: 31202 W Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75 **ADA ID: AC248B2B368D**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **OAKTON HUNT DR** StopSign **WRAYHILL DR** StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Compli	ance Description	Data	Compli	ance Description	
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable R	T?
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	
	X Walk 1 Direction	To SE		X Walk 2 Direction	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	
	X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	
	X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (9	%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk	2?
	Road Slope (%)	9.6	N/A	Clear Space?	
	Road X Slope (%)	6.6	N/A	Clear Space to XWa	alk (in)
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility I	Hazard?
	Obstruction Type			Storm Grate/Utility	Гуре





Total Cost:



3200.00