## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



									/	
Intersection ID: 46820	Main Street: NORWAY_SPRUCE_CT			Cross Street: AZALEA_HILLS_DR				Location:	Ν	
ADA ID: AE8983D0639F	Ramp Type: PerpDiag		Initial	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:		47.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ramp	amp With	N/A	Ramp Length (in)	47.5		Ramp Slope (%)	9.5	
human of the		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	31.0	Yes	Ramp XSlope (%)	0.2	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
10 100				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
2		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	5 Start Kill			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A A A	A LOAD IN			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Charles a	S. SHILLS DO			N/A	Shared Landing?	N/A				
1 HANKA	1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
a made of	AND	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
and we have the	A MAR			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
A DAMA AND A					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
A TRANSFORMENT AND				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	AZALEA HILLS DR	-			X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	0.3	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	0.4	
Street 2 Name	NORWAY SPRUCE CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	1.4	N/A	Clear Space?	N/A	
					Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

s Surface Condition? (G/P)

Good

