

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									I
Intersection ID: 13932	Main Street: LORNA_ST			Cross Street: COMMONWEALTH_AV					E
ADA ID: B02BEACB300F	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	No. A	Possible Solutions:					Compliance Description Data		
	REAL SEC	Remove & Replace Entire Ramp.	N/A	Ramp Ler	igth (in)	25.5	Yes	Ramp Slope (%)	7.7
	ROLL		Yes	-	• • • •	48.0	No	Ramp XSlope (%)	3.7
			N/A	Flare Type	e LT	N/A	N/A	Flare Type RT	N/A
	Mari A		N/A	Flare Slop	be LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1		N/A	Flare Trav	ersable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Brad		N/A	Landing L	ength (in)	N/A	N/A	DWS Provided?	N/A
	1 1	Surveyor Notes:	N/A	Landing V	/idth (in)	N/A	N/A	DWS Contrast?	N/A
	2 all	N/A	N/A	Landing S	lope (%)	N/A	N/A	DWS Length (in)	N/A
Contraction of Contraction	Ter		N/A	Landing X	Slope (%)	N/A	N/A	DWS Full Width?	N/A
E L			N/A	Landing C	urb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared La	inding?	N/A			
A		PROW/ADA:	N/A	Gutter Po	nding?	N/A	N/A	Gutter Slope (%)	N/A
the first		Not Found, R304.5.3	N/A	Gutter Lip	Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	TIT BOL AN		N/A	Painted X	Walk1?	No	N/A	Painted X Walk2?	N/A
Del RESTIN				X Walk 1 I	Direction	To NW		X Walk 2 Direction	N/A
			N/A	X Walk 1	Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LORNA ST			X Walk 1	Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign			X Walk 12	X Slope (%)	2.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp insi	de XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slop	be (%)	N/A	N/A	Clear Space?	N/A
				Road X SI	ope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstr	ructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstructio	on Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

