cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16464	Main Street: MANDARIN_BV			Stroot.		Location:	NW		
				Cross Street: MONROE_RD					
ADA ID: B40E50341F2B Ramp Type: ParaDiag		Initial	nitial Pass/Fail: Fail Overall Compliance: No				Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
And an s		Remove & Replace Curb Ramp	With	N/A	Ramp Length LT (in)	52.0	N/A	Ramp Length RT (in)	58.0
		Two New Directional Ramps or		Yes	Ramp Width LT (in)	85.0	Yes	Ramp Width RT (in)	84.0
		Equivalent.		No	Ramp Slope LT (%)	9.2	Yes	Ramp Slope RT (%)	4.7
	3/ /			Yes	Ramp XSlope LT (%)	1.1	No	Ramp XSlope RT (%)	2.6
	TAR			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
all all		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E /	100	RT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6. / b.	the state of the			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A	Con the second			N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.3.2, R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	0.4
Street 1 Name	MONROE RD				X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	0.4
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	MANDARIN BV				Road Slope (%)	1.3	N/A	Clear Space?	N/A
Stop Condition-Street 2	StopSign				Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$ 3	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good







N/A

Curb Slope (%)

10.9