cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47977	Main St	reet: AVALY LN	Cross	Cross Street: SPRINGS MILL RD				Location:	SW
ADA ID: B52542E52158	Ramp Type: BlendTrans1		Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
SPRINGS MILL		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	78.0	Yes	BlendTrans Slope (%)	4.1
		Two New Directional Ramps of		No	Ramp Width (in)	44.0	Yes	BlendTrans XSlope (%)	2.0
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		·····, ·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
A - B					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	AVALY LN	_			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	0.9
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	3.4
Street 2 Name	SPRING MILL RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	3.1		Clear Space?	N/A
	_				Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.9