

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24803	Main Street: CHOATE_CR			Cross S	Cross Street: HARLEQUIN_DR				Location:	NW
ADA ID: B5CBEF6480A4	Ramp Type: Directional1			Initial P	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description		
13 Mas	1110	Remove & Replace E	ntire Ramp		N/A	Ramp Length (in)	66.0	N/A	Grade Break?	N/A
	111				No	Ramp Width (in)	40.0	N/A	Grade Break Slope (%)	0.0
	<u>s</u>				No	Ramp Slope (%)	10.4	N/A	Grade Break XSlope (%)	0.0
	71				No	Ramp XSlope (%)	4.5			
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	10				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
Contraction of the second seco		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
the second se					N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
AND A DECEMBER	Carl and the				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
What has the second	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	R304.5.1, R304.2.2, F	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	,,, .			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	1.5	
Street 1 Name HA	RLEQUIN DR					X Walk 1 Direction	To E		Road X Slope (%)	2.2
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.2	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	5.9

