

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 26731 Main Street: MISTY_HILL_LN Cross Street: SURREYHILL_CT Location: N

ADA ID: B5F426A5A6D9 Ramp Type: BlendTrans1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

MISTY HILL LN
StopSign
SURREYHILL CT
None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Ramp Length (in) Yes N/A 48.5 BlendTrans Slope (%) 3.4 48.0 Yes Yes Ramp Width (in) BlendTrans XSlope (%) 0.2 N/A N/A Flare Type LT Sloped Flare Type RT Sloped N/A Flare Slope LT (%) N/A Flare Slope RT (%) 1.8 1.8 N/A Flare Traversable LT? No N/A Flare Traversable RT? No Landing Length (in) 48.0 No DWS Provided? Yes No Yes Landing Width (in) 48.0 N/A **DWS Contrast?** No 0.7 N/A Yes Landing Slope (%) DWS Length (in) N/A N/A Yes Landing X Slope (%) 0.3 DWS Full Width? No N/A Landing Curb? (Y/N) No N/A DWS Offset (in) N/A N/A Shared Landing? No **Gutter Ponding?** No Yes Gutter Slope (%) Yes 2.9 Yes Gutter Lip Ht (in) 0.0 Yes Gutter X Slope (%) 2.0 N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SE X Walk 2 Direction To SW N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.6 X Walk 2 Slope (%) 1.5 X Walk 1 X Slope (%) 8.0 X Walk 2 X Slope (%) 1.8 N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 3.4 Clear Space? Yes Road X Slope (%) 2.5 N/A Clear Space to XWalk (in) N/A No Yes Any Obstructions? Yes Storm Grate/Utility Hazard? No Obstruction Type Storm Grate/Utility Type N/A N/A

Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

10.0





