

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43744 Main Street: RED_CLAY_LN Cross Street: EARTHENWARE_DR Location: E

ADA ID: B673872A774A Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

RED CLAY LN StopSign EARTHENWARE DR None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost: \$ 3200.00

ComplianceDescriptionDataComplianceDescriptionN/ARamp Length (in)50.0NoRamp Slope (9)	5) 18.1
N/A Ramp Length (III) 50.0 No Ramp Slope (3	,
No Ramp Width (in) 46.5 Yes Ramp XSlope	0/\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	,
N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A N/A Flare Slope R7	
N/A Flare Traversable LT? N/A N/A Flare Traversa	
N/A Landing Length (in) N/A N/A DWS Provided	
N/A Landing Width (in) N/A N/A DWS Contrast	? N/A
N/A Landing Slope (%) N/A N/A DWS Length (i	n) N/A
N/A Landing X Slope (%) N/A N/A DWS Full Widt	h? N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (ir) N/A
N/A Shared Landing? N/A	
N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A
N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope	(%) N/A
N/A Painted X Walk1? No N/A Painted X Walk	:2? N o
X Walk 1 Direction To NW X Walk 2 Direction	tion To SW
N/A X Walk 1 Width (in) N/A N/A X Walk 2 Widtl	(in) N/A
X Walk 1 Slope (%) 2.1 X Walk 2 Slope	(%) 2.1
X Walk 1 X Slope (%) 3.1 X Walk 2 X Slo	pe (%) 2.3
N/A Ramp inside XWalk1? N/A N/A Ramp inside X	Walk2? N/A
Road Slope (%) 1.3 N/A Clear Space?	N/A
Road X Slope (%) 3.0 N/A Clear Space to	XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/U	ility Hazard? N/A
Obstruction Type Storm Grate/U	ility Type
N/A	N/A
Yes Surface Condi	ion? (G/P) Good





