

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47651Main Street:MULLAN_LNCross Street:MORAY_CTLocation:SEADA ID: B7EB9D6D259ERamp Type:PerpInitial Pass/Fail:PassOverall Compliance:NoSeverity Score:0.25

Codes/Mitigation Info/Possible Solution



	The second secon
Street 1 Name	MORAY CT
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

_		
	Possible Solutions:	
The State of the S	Remove & Replace Entire Ramp. Remove & Replace Gutter.	
100 mm		
Section Section		
5	Surveyor Notes:	
A SEC	N/A	
100		
100	PROW/ADA:	
	Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para	

Total Cost:



2600.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	47.5	Yes	Ramp	Slope (%)	5.7
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	2.7
N/A	Flare Type LT	Sloped	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	9.1	Yes	Flare	Slope RT (%)	3.1
N/A	Flare Traversable LT?	Yes	N/A	Flare	Traversable RT?	Yes
Yes	Landing Length (in)	48.0	Yes	DWS	Provided?	Yes
Yes	Landing Width (in)	48.0	Yes	DWS	Contrast?	Yes
No	Landing Slope (%)	3.2	Yes	DWS	Length (in)	24.5
No	Landing X Slope (%)	3.3	Yes	DWS	Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS	Offset (in)	0.0
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	Yes	Gutte	r Slope (%)	0.5
Yes	Gutter Lip Ht (in)	0.0	No	Gutte	r X Slope (%)	2.7
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.1		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.5		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storn	n Grate/Utility Hazard?	No
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good