cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 3852 | Main Street: DERBY_MEADOWS_CT | | Cross Street: WOODCOCK_LN | | Location: | SE | |
|---|--|----------------|--|---------|-----------------------------|-------|--|
| DA ID: B8363E310D0E Ramp Type: Perp | | Initial Pass/F | Initial Pass/Fail: Fail Overall Compliance: No | | No Severity Score: | 13.75 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | |
| | Possible Solutions: | Com | Compliance Description Data | | Compliance Description Data | | |
| | Remove & Replace Entire Ram |). N/A | Ramp Length (in) | 48.0 No | Ramp Slope (%) | 8.4 | |
| | | Yes | Ramp Width (in) | 48.0 No | Ramp XSlope (%) | 2.8 | |
| | and the second s | N/A | Flare Type LT | N/A N/A | Flare Type RT | N/A | |
| | | N/A | Flare Slope LT (%) | N/A N/A | Flare Slope RT (%) | N/A | |
| A TENT MEADOW | TB_BT | N/A | Flare Traversable LT? | N/A N/A | Flare Traversable RT? | N/A | |
| TERBY MENDING | | N/A | Landing Length (in) | N/A N/A | DWS Provided? | N/A | |
| | Surveyor Notes: | N/A | Landing Width (in) | N/A N/A | DWS Contrast? | N/A | |
| | N/A | N/A | Landing Slope (%) | N/A N/A | DWS Length (in) | N/A | |
| | | N/A | Landing X Slope (%) | N/A N/A | DWS Full Width? | N/A | |
| | | N/A | Landing Curb? (Y/N) | N/A N/A | DWS Offset (in) | N/A | |
| | 1.2 | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | N/A | Gutter Ponding? | N/A N/A | Gutter Slope (%) | N/A | |
| | Not Found, R304.2.2, R304.5.3 | N/A | Gutter Lip Ht (in) | 2.0 N/A | Gutter X Slope (%) | N/A | |
| A POINT AND A POINT A | , | N/A | Painted X Walk1? | No N/A | Painted X Walk2? | N/A | |
| | The P | | X Walk 1 Direction | то W | X Walk 2 Direction | N/A | |
| | 1 | N/A | X Walk 1 Width (in) | N/A N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name WOODCO | COCK LN | | X Walk 1 Slope (%) | 1.7 | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 2 | None | | X Walk 1 X Slope (%) | 1.6 | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | N/A | Ramp inside XWalk1? | N/A N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | N/A | | Road Slope (%) | 1.6 N/A | Clear Space? | N/A | |
| | | | Road X Slope (%) | 1.7 N/A | Clear Space to XWalk (in) | N/A | |
| | | N/A | Any Obstructions? | N/A N/A | Storm Grate/Utility Hazard? | N/A | |
| | Total Cost: \$ | 1850.00 | Obstruction Type | | Storm Grate/Utility Type | | |
| | | | | N/A | | N/A | |

Yes Surface Condition? (G/P) Good

