cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 10019157 Main Street: TIPPAH_PARK_CT | | | Cross S | Street: | N/A | Location: | NW | | | |
|---|-------------------|---------------------------------------|-----------|---|-----------------------|-----------------------------|------|-----------------------------|------|--|
| ADA ID: B902F5CD2525 Ramp Type: Perp | | | Initial P | ass/Fa | ail: Fail Overall (| o Severity Score: | 1.25 | | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: | | Compliance Description | | Data Compliance Description | | Data | | |
| | 1 - mining | Remove & Replace Entire Ramp | - | N/A | Ramp Length (in) | 79.0 | Yes | Ramp Slope (%) | 6.4 | |
| | (mar 18 18 1 | | | Yes | Ramp Width (in) | 58.0 | No | Ramp XSlope (%) | 4.8 | |
| Alter Sector | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| Non N | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| All I and Bran | | 3 | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| 6 | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | The second second | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| TIPPo ta | 1 | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| PROW/ADA: R304.5.3 | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | | | N/A | Shared Landing? | N/A | | | | |
| | | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | | | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | N/A | |
| Sites and the second | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | TIPPAH PARK CT | - | | | X Walk 1 Slope (%) | 1.0 | | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 7.3 | | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | N/A | | | | , Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | N/A | | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | · · · · · · · · · · · · · · · · · · · | | | | N/A | | | N/A | |
| | | | | | | 17/1 | 1 | | 10/5 | |