cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45882	section ID: 45882 Main Street: HOMESTEAD_GLEN_BV					Cross Street: VALLEYDALE_RD				S	
ADA ID: B9B83892B5EE	E Ramp Ty	Ramp Type: Combination1				ail: Fail Overall (nce: N	o Severity Score:	22.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	N BIA	Possible Solutions:		Compliance Description		Data Compliance Description			Data		
	Stat 15	Remove & Replace	Entire Ramp		N/A	Ramp Length LT (in)	51.0	N/A	Ramp Length RT (in)	48.0	
A ISIN					Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	58.0	
					No	Ramp Slope LT (%)	10.2	Yes	Ramp Slope RT (%)	1.4	
<u>b</u>					Yes	Ramp XSlope LT (%)	0.6	No	Ramp XSlope RT (%)	2.1	
	Bill the second				N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	3.5	
t.	King &				No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.6	
<u>k</u> 😵	COLOR AND	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	A RAN	RP & RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	6				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
AVER STATE					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Charles in 1	1 11 1				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ACTIVE 3	1. K	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
This will be	. with the man	Not Found, R304.5.	1. R304.3.2.		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
and the second second	ARE NOT AREA	R304.5.3	,,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and the second second	LUCK LAND				N/A	Shared Landing?	N/A				
A LAND	TRACK WEAK			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	HOMESTEAD GLEN BV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 18	300.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
								N/A	Any Obstruction?	N/A	
A Contraction of the second se									Obstruction Type		
				Mar day						N/A	
				and the second s	Party and a second			NI/A	Storm Croto/Utility/Uszard2		

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 9.6





