

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10016795Main Street: HARRIS_STATION_BVCross Street: N/ALocation:SWADA ID: BAFAE94A40E0Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name HARRIS STATION BV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

| Possible Solutions: | | | | | |
|-------------------------------|--|--|--|--|--|
| Remove & Replace Entire Ramp. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Surveyor Notes: | | | | | |
| N/A | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| PROW/ADA: | | | | | |
| Not Found, R304.5.1 | | | | | |
| | | | | | |
| | | | | | |

PROW/ADA: N/A

Not Found, R304.5.1 N/A

N/A

N/A

Total Cost: \$ 1850.00

| Compliance Description Data Compliance Description Data | | | | | | |
|---|-----------------------|-------|-----|-----------------------------|------|--|
| N/A | Ramp Length (in) | 72.0 | Yes | Ramp Slope (%) | 6.4 | |
| No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 1.0 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 0.9 | | X Walk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 2.2 | | X Walk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | | |





