

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32275 Main	Main Street: PRESCOTT_HILL_AV			Cross Street: SPRINGWELL_ST				SW	
ADA ID: BBB5463B432C Ram	Ramp Type: Perp			ail: Fail Overall (o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:						liance Description	Data		
	Remove & Replace Entire Ram	b .	N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	10.5	
		• •	Yes	Ramp Width (in)	63.0	Yes	Ramp XSlope (%)	0.6	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	120		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
AN TOTAK LET			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	7 -		N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name PRESCOTT HILL AV				X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2 No	ne			X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A	
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good

