

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17494	Main Street: MONROE_RD			Cross Street: FOREST_WAY_DR				Location: E		
ADA ID: BC71C009E4E0	Ramp Ty	Initial P	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 1.25		1.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
		Possible Solutions:		Compliance Description Data Compli				iance Description Data		
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	112.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	70.5	N/A	Grade Break Slope (%)	0.0	
	10			Yes	Ramp Slope (%)	1.7	N/A	Grade Break XSlope (%)	0.0	
	100			No	Ramp XSlope (%)	2.9				
	WAY DR			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E B B B B B	ST LE SA -			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
the leg of the	Ser Contraction	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
6	and that show			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
6. B	- Bernan			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
The I day of the	The AL			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	TE CALL	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
The second is	A REALEMENT			N/A	Painted X Walk1?	No		Road Slope (%)	0.7	
Street 1 Name	FOREST WAY DR				X Walk 1 Direction	To NW		Road X Slope (%)	3.0	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.0	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	3.4	

